

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-019770**Date Inspected:** 14-Jan-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See Below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector, Mike Hasler was present during the times noted above for observations and testing relative to the work being performed.

Bay 8

This QA inspector performed a random observation for the Orthotropic Bridge Girders (OBG) located at ZPMC Shanghai China. During the observation performed it was noted that at Bay 8, ZPMC was in process of welding bike path assembly welds. ZPMC Certified Welding Inspector Liu Fa Wen was present at this time of this observation and informed this QA inspector of the work that is in process. It was stated that ZPMC had 2 welders and identified the welders by ZPMC welder identification number appointed to then by ZPMC. This QA inspector verified this information for the following location;

Weld-BK004A3-063-002

WPS-B-P-2211-TC-U4c

Welder-040673

1G/ CJP/ SMAW

CWI Huang Min

CWR2751-R0

Weld-BK004A2-064-002, 013, 021

WPS-345-SMAW-2G(2F)-Repair

Welder-058009

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

2F/SMAW

The following digital picture illustrates typical CWR2751-R0

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

“As noted within the contents of this report.”

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

| | | |
|----------------------|-------------|-----------------------------|
| Inspected By: | Hasler,Mike | Quality Assurance Inspector |
| Reviewed By: | Riley,Ken | QA Reviewer |
